




Mounting Instructions 2000 Series Workstation Lighting

- * The light is designed to be mounted using the 2 (.375 dia.) mounting holes shown on the drawing below.
- * (2) 1/4-20 screws or 2 (3 lobed) knobs are required to safely mount the light to the horizontal mounting track of the workstation.



* Installation *

- 1 . Insert the (2) 1/4-20 Screws through the mounting holes on each end of the fixture.
- 2 . Insert the Tee nuts into the horizontal mounting track.
- 3 . Insert the 1/4-20 screws into the tee nuts and tighten securely.

Note: All screws, knobs, or tee nuts are not provided with each light, unless requested.

" Caution "

- * Injury to person and damage to the light and/or mounting surface may result if the light is pulled from the surface.
- * Always mount light only to a surface that is mechanically sound to reduce the likelihood of such injury or damage.